



THE BELT RAILWAY COMPANY OF CHICAGO

Yardmaster Notice

2023-001

Effective, Monday March 27th. 0001

To: All Yardmasters

Subject: Routing of locomotives through west yard

Inbound trains yarding in the West Receiving Yard must no longer be routed through the west yard when parking their locomotives, alternative routes through the West Receiving Yard or the South Thoroughfare must be utilized as the route when sending power to the Diesel Shop, Industry Lead, Etc.

Yardmaster Notices in Effect:

2016	001, 002
2019	002, 003,
2020	001, 004, 005
2021	001
2023	001