



BRC GENERAL NOTICE

#2026 - 004

Effective 0001 Saturday March 7th, 2026.

To: All Employees.

Subject: Do Not Hump Rail Cars:

Applicability: DO NOT HUMP- *Cars that cannot be humped unless otherwise specified.*

Process for Do Not Hump Cars

1. Identification:

If a car is designated as "Do Not Hump" in the TYT or Belt Apps systems, it must be treated as such and shoved into a bowl track.

2. Error Handling:

If there is a perceived error in the designation, the Car Foreman on duty must visually inspect the car.

If the Car Foreman determines the car is safe to hump, they must communicate this directly to the Terminal Manager.

3. Designation Removal:

If the Car Foreman decides the "Do Not Hump" designation can be removed, the Terminal Manager must notify the Director of Car Operations, Kevin Billingsley, via email with the car number and details of the removal for further investigation.

Exception: Cars may be placed on designated mechanical repair tracks when directed by Mechanical Personnel.

End of General Notice

Jason Charbonneau
Superintendent

BRC General Notices in Effect:

Year of Issuance	Numbers
2026	001, 002, 003, 004
2025	003, 004, 006